



STATE OF LIBYA
MINISTRY OF TRANSPORTATION

دولة ليبيا
وزارة المواصلات

TEL/FAX: + 218 21 5632338
AFS: HLLLYNYN.
Email: ais@caa.gov.ly
Website: www.Caa.gov.ly/ais/

CIVIL AVIATION AUTHORITY
AIR NAVIGATION SERVICES DEPARTMENT
AERONAUTICAL INFORMATION SERVICE
(AIS)

AIP
Supplement 5/24
15 JUL 2024

- The Following Supplements Are Still Valid At 06:30 ON 15 JUL 2024 , Supplement Not Included Have Either Been Cancelled, Time Expired, Superseded By Another AIP Supplement Or Incorporated In The AIP Libya.
- The checklist displays both AIRAC and NON AIRAC AIP SUP starting from the oldest.

NR/YEAR	Part	Details	WEF	Till
SUP 3/15	AD Kufra	HLKF Hours Of Service Are Now H24.	20 OCT 2015	UFN
SUP 1/17	AD Zintan	HLZN Aerodrome Geographical And Administrative Data.	21 JUN 2017	PERM
SUP 4/17	AD Ghardabiya	HLGD 1- national flights Only 2-AD Fire Fighting CAT (5).	14 SEP 2017	UFN
SUP 6/17	AD Labraq HLLQ	1- LAQ VOR/DME Completely Withdrawn 2-AD Fire Fighting CAT (5). 3-NEW DVOR/DME Installed FRQ 116.3 MHZ COOR N324730.48 E0215714.38 Operational Under Test.	14 SEP 2017	PERM
SUP 7/17	AD Sebha	HLLS 1- First 300M OF RWY 13 CLSD 2-AD Fire Fighting CAT (6).	14 SEP 2017	UFN
SUP 8/17	AD Tripoli HLLT	1- REF AIP PAGE AD2 HLLT-6 and All Other Instrument Charts For HLLT AD TWR Main FRQ 118.100 Instead Of 120.100 2-AD Fire Fighting CAT (8).	14 SEP 2017	PERM
SUP 10/17	AD Ghadames	HLTD AD Fire Fighting CAT (5).	14 SEB 2017	PERM
SUP 11/17	AD Ubari	HLUB AD OPS SR/SS.	14 SEB 2017	UFN
SUP 2/18	ENR	ZAW VOR/DME 117.7 MHZ UNSERVICEABLE.	06 MAR 2018	UFN
SUP 3/18	ENR	WLD VOR/DME 115.9 MHZ UNSERVICEABLE.	06 MAR 2018	UFN
SUP 4/18	ENR	IZD VOR/DME 116.5 MHZ UNSERVICEABLE.	06 MAR 2018	UFN
SUP 7/18	ENR	NEW WAYPOINT (RAKMU) POSITION N331816 E0242740 HLLLFIR/HECCFIR BOUNDRY, LOWER/UPPER LIMIT FL300/310, ANY WESTBOUND TRAFFIC ENTERS HLLLFIR AT NON STANDARD LEVEL TO EXPECT LEVEL CHANGE AS SOON AS POSSIBLE AFTER HAVING ESTABLISHED CONTACT WITH BENGAZI CONTROL .	06 MAR 2018	PERM
SUP 13/18	AD Ubari HLUB	AD Available For National FLT'S Only, Prior Permission To Operate From TO AD IS Required By Notification Via AFTN AFS (HLLTYAYX) or FAX +218 21 3618075	06 MAR 2018	UFN
SUP 17/18	AD Tamanhint	HLTM Aerodrome Geographical and Administrative Data.	08 MAY 2018	PERM
SUP 1/21	ENR	VHF 125.80 , 133.60 And 136.15 ARE UNSERVICEABLE Ref AIP PAGE ENR 6.2-1.	28 JAN 2021	UFN

SUP 2/21	AD Tripoli HLLT	1- D/L FRQ 435 MHZ WITHDRAWN 2- REF AIP PAGES AD2 HLLT-33 AND 41 ILS DME RWY 27 RESPECTIVELY MISSED APPROACH CHANGED AS FOLLOWS: CLIMB STRAIGHT AHEAD TO 1500FT MSL THEN TURN RIGHT AND PROCEED TO PE/L CLIMBING TO 2000FT MSL AND HOLD 3-PN/L FRQ 344KHz Installed COOR. N324546.88 E0130911.87 (Operating Under Test) 4-IAP CHART TPI VOR/DME RWY27 And RWY 09 IS SUSPENDED.	28 JAN 2021	PERM
SUP 3/21	AD Ghat HLGT	AD Available For National FLT'S Only Prior Permission To Operate From To AD Is Required By Advance Notification Via AFTN AFS (HLLTYAYX) or FAX +218 21 3618075 .	28 JAN 2021	UFN
SUP 9/21	AD Labraq	HLLQ ILB ILS RWY 28 Operating But Ground Checked Only.	01 JUN 2021	UFN
SUP 10/21	AD Tripoli	HLLT AD CLOSED.	01 JUN 2021	UFN
SUP 11/21	ENR	Secondary Surveillance Radar (SSR) U/S.	01 JUN 2021	UFN
SUP 13/21	ENR	The following temporary prohibited area within HLLL FIR 322826.95N E0114032.17 324025.55N E0113302.20 324933.62N E0115741.66 322843.597N E0122241.673 321224.363N E0121145.086 321319.03N E0113531.26 322826.95N E0114032.17 From GND to 45000FT	09 JUN 2021	UFN
SUP 14/21	ENR	The following temporary restricted area within HLLL FIR N32 22 E015 10 -N31 50 E014 27 N31 31 E014 45-N30 36 E015 25 N31 12 E016 38-N31 23 E015 34 N32 22 E015 10 GND to 25000FT	15 JUN 2021	UFN
SUP 2/22	AD Sebha	HLLS FIRST 300 M OF RWY 31 CLSD.	14 FEB 2022	UFN
SUP 6/22	AD Tobruk	HLTQ VOR/DME FRQ 112.3 CH70X Operating But Ground Checked Only.	31 MAR 2022	UFN
SUP 7/22	AD Benina	HLLB VOR/DME FRQ 117.4 CH121X Operating BUT Ground Checked Only.	31 MAR 2022	UFN
SUP 10/22	AD Ghadames	HLTD VOR/DME FRQ 115.8 CH105X Operating But Ground Checked Only.	31 MAR 2022	UFN
SUP 11/22	AD Ghat	HLGT DVOR/DME FRQ 114.8 CH95X Operating But Ground Checked Only.	31 MAR 2022	UFN
SUP 3/23	AD Ghadames	HLTD AD CLOSED	11 MAY 2023	UFN
AIRAC SUP 1/23	AD Zintan	HLZN New Instrument Approach Charts VOR/DME ZNT FRQ 112.5 MHZ COOR 31.48.29.15N012.15.50.07E For RWY 02/20	15 JUN 2023	PERM
AIRAC SUP 1/24	ENR	1. Withdrawn of Restricted area HL-R42 2. Rename Way Point RIGED to read KUNEB 3. Realignment the lateral limits of the Tripoli FIR/UIR	22 FEB 2024	PERM
SUP 1/24	AD Ubari	HLUB AD Category For Fire Fighting CAT 6	10 FEB 2024	PERM

SUP 2/24	AD Zwara HLZW	1. Operational Hours SR/SS 2.ATS AVBL Upon Request 3. AD Category For Fire Fighting CAT 5	12 FEB 2024	UFN
SUP 3/24	ENR	Temporary restricted area N311600 E0161000 N310800 E0170700 N303000 E0170000 N304200 E0160500 N311600 E0161000 From GND to FL195	03 APR 2024	UFN
AIRAC SUP 3/24	AD ERAWN HLER	NEW FOUR LETTER LOCATION INDICATOR HLER ALLOCATED TO ERAWN AD. ARP 255239.34N0110259.7E ELEVATION 1850 FT OPERATIONAL HOURS SR/SS Category for fire Fighting CAT 4 RWY MAG 03/21 RWY DIMENSION 30 × 2100 RWY SURFACE SAND	16 MAY 2024	PERM
AIRAC SUP 4/24	AD ATSHAN HLAT	NEW FOUR LETTER LOCATION INDICATOR HLAT ALLOCATED TO ATSHAN AD. ARP 271230.91N0103112.88E ELEVATION 1444 FT AMSL OPERATIONAL HOURS SR/SS Category for fire Fighting CAT 4 RWY MAG 16/34 RWY DIMENSION 30 × 1195 RWY SURFACE SAND	16 MAY 2024	PERM
SUP 4/24	ENR	Area navigation route M600 segment Between ZAWIA and GALPO Closed from GND to FT45000	18 MAY 2024	UFN
AIRAC SUP 5/24	AD Mitiga HLLM	Update IAC RWY 10/28 1.Instrument Approach Chart VOR DME RWY 10 2.Instrument Approach Chart VOR DME RWY 28 3. Instrument Approach Chart ILS or LOC RWY 28	11 JUL 2024	PERM
SUP 5/24	ENR,AD	Index of the AIP SUP	15 JUL 2024	UFN

- This AIP SUP Replaces SUP 1/23 .
- This AIP SUP Contains 3 Pages .

=====END=====